

CABLE SECRETARIAT DISSEMINATION		CLASSIFIED MESSAGE	TOTAL COPIES	ROUTING AND/OR INITIALS - SEEN BY	
PERSON/UNIT NOTIFIED		SECRET (When Filled In) GROUP 1 EXCLUDED FROM AUTOMATIC DECLASSIFICATION	1		6
Approved For Release 2001/07/16 : CIA-RDP78-06505A000800080055-1			3		7
ADVANCE COPY <input type="checkbox"/> ISSUED <input type="checkbox"/> SLOTTED <input type="checkbox"/>			4		8
BY: _____ AT: _____ Z			5		9
DISSEM BY: <u>4</u> PER _____ # _____					10
ACTION <u>Comm 8</u> <input type="checkbox"/> RID COPY		REPRODUCTION OF THIS COPY PROHIBITED INDEX <input type="checkbox"/> YES <input type="checkbox"/> NO CLASSIFY TO FILE NO. _____ X-REF TO FILE NO. _____ FILE RID <input type="checkbox"/> RET. TO _____ BRANCH <input type="checkbox"/> DESTROY <input type="checkbox"/> SIG.			
INFO: _____		FILE, _____ VR, <u>NE 8, LOGS 4</u>			

25X1A

25X1A

S E C R E T 181443Z MAR 68 CITE [REDACTED]

110

18 Mar 68 72548

DIRECTOR

25X1A

25X1A

1. EXPERIENCING DIFFICULTY WITH CALCIUM DEPOSIT BUILD-UP IN [REDACTED] AIRCONDITIONING WATER COOLING TOWER. SUITABLE WATER SOFTENING UNIT LOCALLY AVAILABLE FROM [REDACTED] COMPANY FOR 700 DOLLARS.

2. REQUEST PERMISSION TO PURCHASE AND INSTALL. FUNDS CAN BE MADE AVAILABLE.

S E C R E T

BT

25X1A

25X1A

Not acceptable. Looks like sales talk to layman. Not enough info for complete evaluation.

RECD
C
DC
EX
C/RE
RO
File

SECRET

25X1A	DISPATCH		CLASSIFICATION SECRET	PROCESSING ACTION
	TO Chief [REDACTED]			MARKED FOR INDEXING
25X1A	INFO.			NO INDEXING REQUIRED
	FROM Chief [REDACTED] <i>am</i>			ONLY QUALIFIED DESK CAN JUDGE INDEXING
	SUBJECT General - Logistics/Supply Specific - Request for Replacement Air Conditioners			MICROFILM
ACTION REQUIRED - REFERENCES				
<p><i>Voltage?</i></p> <p>1. Attached is requisition 122-814-65 for 17 Air Conditioners, 2 ton, 50/60 cycle.</p> <p>2. Of the above 17 Air Conditioners, 15 are replacements for units presently in use and certified by the Public Works Officer as uneconomically repairable. "In Use" units are at least 9 years old and will average \$65 to \$75 each to put in C-1 condition. The 2 additional units (making a total of 17) will be issued to Public Works for rotation as spares; thus, allowing a planned maintenance program.</p> <p>3. With the creation of [REDACTED] communications equipment and personnel have increased to a point that 3/4 ton units are no longer efficient; therefore, 2 ton units are being requested as replacements for present units.</p> <p>4. Along with air conditioners, it would be appreciated if Headquarters would furnish an appropriate manufacturers list of recommended spare parts.</p> <p>[REDACTED]</p> <p>COORD: [REDACTED] ENG.</p> <p>Distribution: Orig. & 2 [REDACTED] w/att. 1 [REDACTED] ng.</p> <p>[REDACTED]</p> <p>787 2</p> <p>RECORDED OL REGISTRY</p> <p>787 2</p> <p>C/REC DC/REC EQ [REDACTED] C/ACQ C/CE C/ [REDACTED] CENTRAL FILE</p> <p>3 November 1964</p> <p>HQS FILE NUMBER</p> <p>(61)</p>				
CROSS REFERENCE TO		DISPATCH SYMBOL AND NUMBER [REDACTED]		DATE
GROUP 1 EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION		CLASSIFICATION SECRET		